

WORKS CARRIED OUT ON MY AMNESIA FROM 2008 TO 2010

HULL AND SUPERSTRUCTURE

Full paint of hull and superstructure
Under hull antifouling
All anodes replaced
Propellor coated
Rebuild of swim platform
Fleet 77 satellite communications installed
Remodel of flying bridge lounge area
Full out of water survey in 2009 to Bureau Veritas Class requirements
In hull storage and machinery spaces painted
Flying bridge guest service area installed

INTERIOR AND GUEST ACCOMMODATION

Interior guest accommodation re modeled and painted
Interior furnishings replaced with new furniture and décor
Massage room installed
All guest cabins installed with entertainment systems
Multi zone sound system installed
Bar installed
Dinning table installed
New lighting for guest accomadation, Dinning area and interior living areas
New office installed with voice and data capabilities and private entertainment area
All bathrooms re modeled
New teak floors in interior living areas
Safes installed in all guest cabins
Cabin furniture replaced
All floors polished
Samsung split system airconditioner fitted in office

OUTSIDE LIVING AREAS AND DECKS

New teak deck on flying bridge
Bridge deck and lower deck recaulked and sanded with the smallest defect repaired
New sunbrella covered cushions for all outside furniture and lounge areas
New rattan furniture for flying bridge and bridge deck entertainment areas
New outdoor freezer unit on bridge deck
Outside ice machine installed on bridge deck
Sun awning on bridge deck repaired
Outdoor teak dinning table for bridge deck with 8 person capacity
All rail cappings sanded back to bare wood and varnished with epithanes marine varnish 5 coats
New bar fridge installed on flying bridge
New stainless dive ladder
New sunbrella protection cushions for around swim platform
Fishing rod holders for game fishing equipment installed
Two portable seats/ice boxes with matching sunbrella cushions installed

ENGINE ROOM

New compressor installed as back up for airstart system on main engine
Airconditioning system upgraded with new compressors, auto control system, evaporator and fresh and sea water pumps
New northern lights 55kw generator installed
Boudine generator 75kw rebuilt
Main engine checked and new fuel pump installed
Automatic fuel system for daily service tank installed
Automatic system for air start compressors installed
Bilge system checked and upgraded
Fresh water pump system replaced with new pumps
Electrical systems checked and repaired or updated
New batteries
new battery charger
All overboard valves and seacocks removed and checked for out of water survey
Shaft crack tested and seals checked or replaced
New seal in Variable pitch oil delivery box
Shaft alignment checked
Telegraph system repaired and put back into service
All sea chests and strainers checked
All tanks checked and cleaned
Engine room domestic freezer upgraded
Engine room wine chiller and beverage storage upgraded
Two American copeland compressors rebuilt as spares for airconditioning system
Gearbox rebuilt
New injectors installed

WHEEL HOUSE

Fleet 77 voice and data installed
Bridge alarm system checked and upgraded
Telegraph repaired and put back into service
SSB radio repaired
All VHF radios checked and upgraded
New blinds and paint
Electronics distribution board installed
Wireless broad band internet system installed to cover whole vessel
All gauges repaired and checked against engine room data